



# Service Bulletin

File in Section: -

Bulletin No.: 17-NA-326

Date: October, 2017

## TECHNICAL

**Subject:** Rear Brake Squeak Type Noise

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2018				
Chevrolet	Equinox	2018	2018				
Chevrolet	Malibu	2016	2018				

<b>Involved Region or Country</b>	North America and N.A. Export Regions
<b>Condition</b>	Some customers may comment on a squeak type noise heard from the rear brakes when cold. This noise will typically occur on first brake apply when the brakes are cold. <b>Note:</b> This condition may not be duplicated if the brakes are warm.
<b>Correction</b>	Replace the rear brake pads.

### Service Procedure

Refer to *Rear Disc Brake Pads Replacement* in SI.

### Parts Information

Refer to the electronic parts catalog (EPC) for obtaining the latest part number.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2420170	Rear Disc Brake Pads Replacement	Use Published Labor Operation Time

<b>Version</b>	1
<b>Modified</b>	Released October 11, 2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION