

## Clock is slow in vehicles without navigation

---

Topic number	LI54.30-P-066875
Version	4
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	12-08-2017
Validity	BR205/BR253 without navigation (without code 154 and without code 355).
Reason for change	Cause adjusted.
Reason for block	

---

### Complaint:

In vehicles without navigation, the clock is slow and falls behind (by approx. 5-10 minutes per month).

### Cause:

Software in Audio 20. The head unit returns a time with a delay of approx. 1 second to the instrument cluster after each ignition cycle. This time is then distributed in the vehicle by the instrument cluster.

### Remedy:

This is still under investigation, please do not replace any parts.

<b>Symptoms</b>
Communication/information / Information display / Displays / Clock / Too slow