

Audio 20: Fader setting not visible in sound settings

Topic number	LI82.60-P-067428
Version	2
Function group	82.60 Radio, audio, video systems
Date	12-12-2017
Validity	Model 172 with code: 505/520/522
Reason for change	Validity adapted
Reason for block	

Complaint:

In the balance settings, the fader setting can be changed by "pushing" or "pulling" the central operating unit forwards or backwards.

This change is not displayed.

Attachments	
File	Description
BR172_Soundeinstellung.jpg	Balance setting

Cause:

Software release of head unit (A26/17)

Remedy:

In order to restore the "central sound" after a change, push the central operating unit forwards 20 times, then pull it back 10 times.

Long-term remedy:

LI will be updated once Head-Unit software E432.3 is available.

Note: The design does not allow for the fader to be adjusted, so it cannot be changed after the software update.

Symptoms
Communication/information / Entertainment / Audio/Sound / Tone setting malfunction

Control unit/fault code		
Control unit	Fault code	Fault text
A2 / A40/3 / A26/17 - Audio or COMAND (HU5S1)	-	-

Attachments

BR172_Soundeinstellung.jpg:

