

Indicator lamp of A/C button in front climate control operating unit inoperative

Topic number	LI83.30-P-067427
Version	2
Function group	83.30 Air conditioning
Date	12-22-2017
Validity	Model series 205, 213, 238, 253
Reason for change	Damage code adjusted.
Reason for block	

Complaint:

The indicator lamp of the A/C button in the operating unit of the front climate control is inoperative, although the air conditioning system is switched on. The air conditioning system functions correctly.

Attachments	
File	Description
B.mp4	Clip

Cause:

The LED in the A/C control panel may be damaged.

Remedy:

Replace the A/C control panel.

Symptoms
Body / Air conditioning / Air conditioning / EC button lit
Body / Air conditioning / Air conditioning / Air conditioning display error
Body / Interior equipment / Switches, interior, general / Nonfunctional

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
					Reference EPC for A/C control unit part number.	

Attachments	
File	Description
A.jpg	Picture

XENTRY TIPS

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
83-1917	REPLACE OPERATING UNIT OF AIR CONDITIONING SYSTEM		8340U 52	Operating unit for automatic climate control does not operate correctly

WIS-References			
Document number	Title	Note	Allocation
AR83.30-P-6630LW	Remove/install front climate control operating unit	Validity: Model 205, model 213, model 253	Remedy
AR83.30-P-6630LWO	Remove/install front climate control operating unit	Validity: Model 238	Remedy

Attachments

A.jpg:

