

Water deflector/ seal lip tears

Topic number	LI77.50-P-065522
Version	1
Design group	77.50 Hardtop
Date	01-11-2017
Validity	BR190 Coupe
Reason for change	
Reason for block	

Complaint:

Water deflector/ seal lip tears

Attachments	
File	Description
GTS trim.JPG	location

Cause:

Bond between rubber and plastic

Remedy:

Replacement of affected water deflector/ seal lip using part numbers below

Symptoms
Body / Body/Cab / Trim strip/cover / Damaged
Body / Door/Flap / Hood/flap / Trunk lid/liftgate / Seal cracked/torn

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 190 830 76 00			Left water deflector	1		X
A 190 830 77 00			Right water deflector	1		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
68-0000			69B17 42	LEFT SIDE
68-0000			69P17 42	RIGHT

XENTRY TIPS

Attachments

GTS trim.JPG:

