

Creaking noise in center console area on model series 176 and model series 117

Topic number	LI68.20-P-058781
Version	3
Design group	68.20 Center console
Date	01-09-2017
Validity	Model series 176 and 117 up to production date 24.02.2014
Reason for change	Damage code revised
Reason for block	

Complaint:

Creaking noises in area of center console.

Cause:

The trim on the A/C operating unit makes noises.

Attachments	
File	Description
1.JPG	EPC picture

Remedy:

Replacement of trim on A/C operating unit.

Determine the optimized trim parts via the EPC.

Symptoms
Body / Interior equipment / Instrument panel / Noise
Body / Interior equipment / Interior trim / Noise

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			68370 36	Top cover on center console at front

WIS-References			
Document number	Title	Note	Allocation
ar68.20-p-2350nkb	Remove/install cover on center console		Remedy

XENTRY TIPS

Attachments

1.JPG:

