



SI B61 43 17
General electrical System

December 2017
Technical Service

EME FAULT CODES S0728 / S0729

MODEL

I01	X5 40e (F15 PHEV)
-----	-------------------

SITUATION

A fault (S0728 for F15 PHEV or S0729 for i3) is found stored in the EME during ISTA short test. Diagnostic instructions indicate to reprogram EME.

No warning lights or check control messages are shown to the customer.

CAUSE

Erroneous Fault

CORRECTION

No further action necessary.

PROCEDURE

If no other faults are stored and no driveability issues are present, ignore the fault and release the vehicle.

Software correction to eliminate this erroneous fault will be introduced in a future ISTA release.

This fault is not visible to the customer and causes no issues with warning lights or drivability.

A part replacement or software update will not remedy the situation, and are therefore not permitted.

WARRANTY INFORMATION

No warranty fix available or indicated, no warranty information required.

[Copyright ©2017 BMW of North America, Inc.]