

Measure no.

US 63876474-01

Subject

Navigator VI malfunctions

Status date (mm/dd/yy)

12/4/17

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

12/4/17

Created by

Martin Bumba

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K48 K48/11 K48/12 K49 K50

K50/11 K51 K52 K53 K54

K61

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

Various malfunctions in Navigator VI.

Cause

Software error.

Measure

In the GARMIN Express, the updated software 4.90 version is available for the Navigator VI.

In case of problems with the Navigator VI, always check first that the current software is on the device.

The Release Notes are visible during the update process on GARMIN Express.

Complaint**Fault location**

▶

Bluetooth function

Fault type

Failure

Fault place

Cause

#	Fault location	Fault type	Fault place
1	77/52 Navigator		
	Repair Task	Special Clearance	Area
		No	Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------

© 2002-2017 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.