

**Measure no.**

US 63932068-01

**Subject**

Software update for the TFT Instrument cluster

**Status date (mm/dd/yy)**

12/11/17

**Status**

Accepted

**Organization**

US, MOT

**Date created (mm/dd/yy)**

12/11/17

**Created by**

Martin Bumba

**PQM Problem reference****Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

**Vehicles affected****E series**

K50/11 K51

**Engine****Body****Production period (from/to)**

(mm/dd/yy)

**Comment on production period**

/

**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

**Complaint**

No software update for the TFT (Thin-film transistor) instrument cluster.

**Cause**

BMW Motorrad realized the software for the TFT instrument cluster with I level 17-11-501 does not correspond to internal quality guidelines.

**Measure**

For K50/11 and K51 with OE 06AB Connectivity, DO not create a measures plan with ISTA version 4.09.13 (I level 17-11-501). Cancel any measures plan started. Programming and retrofitting these vehicles is expected to be possible with the next I level (1/30/2018).

**Complaint**

Fault location	Fault type	Fault place
62/11 Instrument cluster	Software error	

**Cause**

#	Fault location	Fault type	Fault place
---	----------------	------------	-------------

1 62/11 Instrument cluster

<b>Repair Task</b>	<b>Special Clearance</b>	<b>Area</b>
	No	Electrics/Electronics

---

**Fault code**

---

**Progman / DIS / ISTA / ISTA/P**

<b>System</b>	<b>State</b>	<b>Version</b>
---------------	--------------	----------------

---

© 2002-2017 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.