




Service Bulletin

TECHNICAL

Subject: Instrument Panel (IP) Compartment Door Squeak

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox (VIN X)	2018	2018				
GMC	Terrain	2018	2018				

Involved Region or Country	North America, Middle East, Israel
Condition	Some customers may comment that the IP compartment door (glove box) squeaks when opening or closing.
Cause	This condition may be caused by interface between the plastic hinge components at cold ambient temperatures.
Correction	 <p>Remove the IP compartment door and apply dielectric grease to the two hinges.</p>

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
-----------------	-------------	------------

1030410	Instrument Panel Compartment Door Replacement	Use Published Labor Operation Time
---------	---	------------------------------------

Service Procedure

Refer to *Instrument Panel Compartment Door Replacement* in SI.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from this information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION