




# Service Bulletin

## INFORMATION

**Subject:** Information on Replacement of Park Brake Actuator Unit and/or Electric Park Brake Wire

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2017	2017			All	All
GMC	Acadia (VIN N)	2017	2017			All	All

<b>Involved Region or Country</b>	North America and N.A. Export Regions
<b>Condition</b>	<p>If during service, there is a need to replace the park brake actuator unit and/or the electric park brake wire, the technicians are directed to replace the adjustable retainer (zip tie) on the rear caliper that holds the park brake wire to the actuator unit.</p>  <p>The end of the zip ties are to be cut after the installation is complete. Each vehicle uses 2; 1 for each of the rear calipers. The adjustable retainer will hold the actuator wire retaining clip in position.</p>
<b>Cause</b>	Poor park brake wire retaining clip retention.
<b>Correction</b>	Install a new (12355066) adjustable plastic retainer (zip tie) in the same orientation as the original if the existing tie is removed for any reason.

### Parts Information

Description	Part Number
-------------	-------------

STRAP, PARK/NEU POSN SW WIRE	12355066
------------------------------	----------

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from this information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION