



Service Bulletin

PRELIMINARY INFORMATION

Subject: Rear Vision Camera Display Does Not Fill Radio Display Completely

Models: 2014-2015 Chevrolet Spark
2014-2016 Chevrolet Sonic, Trax
Equipped with RPOs UF7 and UVC

This PI has been revised to add 2016 model year to select vehicles. Please discard PI1284.

Condition/Concern



Some customers may comment that when using the rear vision camera, it only shows on 3/4 of the radio display screen.

Recommendation/Instructions

This is a normal characteristic of this radio display and the rear vision camera. Do not replace any parts.

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from this information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION