



Preliminary Information

PIT5420D Water Rush Or Gurgle Noise From Heater Core

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2017	All	All	LCV	All
GMC	Canyon	2015 - 2017	All	All	LCV	All

Supersession Statement

This PI was superseded to update Recommendation/Instructions. Please discard PIT5420C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

The customer may note a water rush or gurgle type noise from the center dash area.

The technician may isolate this noise to the heater core caused by air in the cooling system.

This can be caused by air injection in the cooling system. This is under evaluation by engineering.

Recommendations / Instructions

Pending release of new surge bottle.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

