



Preliminary Information

PIP5514 Malfunction Indicator Lamp MIL On DTC P0705 Or P0706 Set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Spark	2016 - 2017	All	All	All	MR8
Involved Region or Country	North America					
Additional Options (RPO)	None					
Condition	Some customers may comment on the operation or performance of the CVT7 transmission and/or the SES light is illuminated.					
Cause	Technicians may find codes P0705 or P0706 set in the TCM.					

Correction:

Please follow service information to aid in diagnosing codes P0705 or P0706.

Service Procedure:

If diagnostics leads to replacement of the transmission range sensor engineering is temporarily asking to please replace the TCM also.

Note: This information will be updated after engineering has collected enough data to aid in finding root cause of these codes setting.

Note: Engineering will be requesting both the transmission range sensor and the TCM be returned to the WPC.

Version History

Version	1
Modified	

