



Service Bulletin

INFORMATION

Subject: Information on Incorrect Caution Label Adhered to IBooster

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2017	2017				
Opel	Ampera-e						

Involved Region or Country	North America, Korea, Europe
Condition	 Some customers and/or technicians may comment on a caution label adhered to the top side of the IBooster assembly stating the part installed is used for test trials.

Information	Important: DO Not replace the IBooster for this condition. The supplier mistakenly installed a caution label to the top of the IBooster, even though the parts are good for production.
--------------------	--

Parts Information

No parts are required for this repair.

Service Procedure

Remove and discard the caution label.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION