





# Service Bulletin

## INFORMATION

**Subject:** Security Code Input Message with SPS Error Code E5659, M5304 and/or M5530 During TIS2web Programming

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick Cadillac Chevrolet GMC	All GM Passenger Cars and Trucks	2009	2018			All	All

<b>Involved Region or Country</b>	North America
-----------------------------------	---------------

<p><b>Condition</b></p>	<div style="text-align: center;">  </div> <div style="text-align: center;">  </div> <p>On rare occasions, a security code input message with SPS error code E5659, M5304, and/or M5530 may be displayed in TIS2web when the technician is programming any module.</p> <p>The related screen will also ask the technician to input a security code.</p>
<p><b>Cause</b></p>	<p>This message and related error codes are flags to identify concerns with released content in the service applications.</p> <p>Typically, a technician should never see a Security Code error message as the management of Security Code information is completed prior to release in the SPS Application.</p>
<p><b>Correction</b></p>	<p>Contact the TechLine Customer Support Center (TCSC) so they can guide the technician through the necessary programming procedure.</p>

## Parts Information

No parts needed for this concern.

<p><b>Version</b></p>	<p>1</p>
<p><b>Modified</b></p>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION