



Service Bulletin

PRELIMINARY INFORMATION

Subject: Engineering Information – Hard to Shift or Pops Out of Selected Gear Concerns That Cannot Be Duplicated

Models: 2015-2016 Chevrolet Corvette
Equipped with 7-Speed Manual Transmission (RPOs MEK, MEL or MEP)

This PI has been revised to end the need for information from the field. Please discard PIE0356A.

If you encounter a vehicle with the above concern, refer to the latest version of PI1276.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION