

9003730 06/07/2017 MY17, 18 RU

GPOP - Issue Review System

Part Number: 68359946A\$, RL359946A\$, 68241331A\$, 68368596A\$

Part Description: SI-eVT Transmission - China Variant

Issue Description: The service SI-eVT is shipped with a non-China wiring harness (68241331AC). China market replacement must replace wiring harness with 68368596AA. The China variant 68368596AA wiring harness has an interlock to the electrical charge door.

~ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
