

9003109

06/07/2017

MY12 - 18

All Makes

All Bodies

## **GPOP - Issue Review System**

**Part Number:** 05152029A\$

**Part Description:** Washer Fluid Level Sensor

**Issue Description:** Prior to replacing this part due to "Low Washer Fluid" tell tale light on the dash and the washer fluid bottle is full, please perform this inspection:  
Check if float sensor is rotated off location from the bottle anti-rotation features that surround the SENSOR.  
Check to determine if the issue has been resolved. Continue with repair if necessary.  
Please contact Chris Koch at cell (248) 248-622-6417 if you have questions or need additional information.

~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~