



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-105

Date: November, 2017

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated with One or Multiple DTCs Set

This Bulletin replaces PIP5471 and PIP5449. Please discard PIP5471 and PIP5449.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016	2016			LWN	All
GMC	Canyon	2016	2016			LWN	All

Involved Region or Country	North America
Additional Options (RPOs)	Equipped with Diesel Engine (RPO LWN)
Condition	<p>Some customers may comment on a malfunction indicator lamp illuminated (MIL). During diagnosis a technician may find one or more of the following DTCs set or stored:</p> <ul style="list-style-type: none">• P10D1• P0181• P11B3• P2A00• P113B, P113C, P113D• P0172• P24B1• P2459• P0263• P0266• P0269• P0272• P22FE• P013A, P013B• P200C• P24A4• P11CC• P22A0• P2203
Cause	This may be due to a calibration concern within the Engine Control Module (ECM).
Correction	Refer to Product Emission Campaign #17337. If the campaign has already been completed, refer to SI for additional diagnostics

Version	2
Modified	November 22, 2017 – Revising to update the Condition and remove the Service/Warranty Information.

