

Service Bulletin

File in Section:

Bulletin No.: 17-NA-108

Date: November, 2017

TECHNICAL

Subject: Stalling, Idle Surge During Regeneration, Malfunction Indicator Lamp (MIL) Illuminated - DTCs P0181, P10D1, P11B3, P11CC, P20E8, P22FE, P24B1 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.	woder.	from	to	from	to		
Chevrolet	Colorado Models	2017	2017			LWN	
GMC	Canyon						

Involved Region or Country	North America		
Condition	Some customers may comment that the engine may: Stall Idle surge during regeneration MIL on The Technician may find one or more of the following DTCs set: P0181 P10D1 P11B3 P11CC P20E8 P22FE P24B1		
Cause	This condition may be caused by a software anomaly in the ECM.		
Correction	Refer to Product Emission Campaign #17337. If the campaign has already been completed, refer to SI for additional diagnostics.		

Parts Information

No parts are required for this repair.

Version	2		
Modified	Nov. 22, 2017 - Update Correction section, Removed Warranty and Service section and add DTC P11CC and P11B3.		

