



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-238

Date: November, 2017

TECHNICAL

Subject: Wi-Fi Hotspot and/or Data Sharing Feature Not Working Once it is Turned On

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Sonic, Trax	2018	2018				
GMC	Terrain						

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with RADIO-INFOTAINMENT SYSTEM - 3.X LOW HMI, MIDLEVEL CONNECTIVITY 3.X (RPO IOR)
Condition	Some customers may comment that the Wi-Fi hotspot is turned on but the connected device(s) does not work. 

4846535



4846537

There are two settings icons that have to be toggled (switched) "on" to "green" to enable Wi-Fi: hotspot and share hotspot data.

Note: The Hot Spot feature in the vehicle comes in the off state from the factory.

Cause	This cause is design intended.
Correction	Need to toggle BOTH switches on, the Wi-Fi hotspot and hotspot data on the display.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3480568*	Syncing WIFI Hotspot	0.2 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	2
Modified	November 16, 2017 – Added a Note, updated the Correction and changed the Warranty statement.