

## **Service Bulletin**

File in Section:

Bulletin No.: 17-NA-380

Date: December, 2017


## **TECHNICAL**

**Subject:** Rattle Type Noise Heard from Underneath Vehicle

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	
Chevrolet	Equinox	2018	2018				
GMC	Terrain						

Involved Region or Country  North America and N.A. Export Regions			
Condition	Some customers may comment on a rattle type noise heard from underneath the vehicle.		
Cause	This condition may be caused by the isolator (1) being separated from the cradle hangers (2).	4895575	

Copyright 2017 General Motors LLC. All Rights Reserved.



## **Parts Information**

Causal Part	Description	Part Number	Qty
N/A*	RING	4	11601779

<sup>\*</sup>For warranty transactions, DO NOT mark this/these parts as the Causal Part. Enter the word "Bulletin" in the Causal Part Description free-flow text field.

## **Warranty Information**

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4081948*	Installing Clips onto the Exhaust and Cradle Hanger	0.3 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Released November 28, 2017