



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-368

Date: November, 2017

INFORMATION

Subject: Information On Malfunction Indicator Lamp (MIL) Illuminated - DTC P10D1, P11B3, P11CCSet

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Express	2017	2017			LWN	
GMC	Savana						

Involved Region or Country	North America and Middle East
Condition	Some customers may comment on: <ul style="list-style-type: none"> • MIL is illuminated • Stalling The technician may find one or more of the following DTC set: <ul style="list-style-type: none"> • P10D1 • P11B3 • P11CC
Cause	This condition may be caused by a software anomaly.
Information	Refer to Product Emission Campaign #17337. If the campaign has already been completed, refer to SI for additional diagnostics.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released November 20, 2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION