

Service Bulletin

TECHNICAL

Subject: Diesel Exhaust Fluid Life Percent Missing in Driver Information Center (DIC)

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Equinox	2018	2018			1.6L Diesel Engine (RPO LH7)	

Involved Region or Country	North America and N.A. Export Regions	
Condition	Some customers may comment that the diesel exhaust fluid life percent is missing in the driver information center (DIC).	
Cause	This condition may be caused by a software anomaly.	
Correction	An updated software calibration has been released to address this condition.	

Service Procedure

Refer to *P16 Instrument Cluster: Programming and Setup* in SI.

Important: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	Released December 22, 2017

