



# Service Bulletin

File in Section: -

Bulletin No.: 17-NA-400

Date: December, 2017

## TECHNICAL

**Subject:** Window Regulator Stops Glass Before Achieving Full Up Position

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2018	2018			All	All
GMC	Canyon	2018	2018			All	All

<b>Involved Region or Country</b>	North America and NA Export vehicles
<b>Condition</b>	Some customers may comment on the window not rolling all the way to the top and/or a wind noise originating from the window location.
<b>Cause</b>	This may be due to a calibration concern.
<b>Correction</b>	Update the Body Control Module (BCM) with the latest calibrations.

### Service Procedure

If you encounter a vehicle with the above concern, reprogram the BCM with the latest calibrations. Refer to *K9 Body Control Module: Programming and Setup* in SI.

### Parts Information

No parts needed for this condition.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time

<b>Version</b>	1
<b>Modified</b>	Released December 18 ,2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION