

Service Bulletin

File in Section:

Bulletin No.: 17-NA-114

Date: September, 2017

TECHNICAL

Subject: Oil Leak from Turbocharger Inlet or Outlet Duct

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado Express	2016	2018			LWN	All
GMC	Canyon Savana	2016	2018			LWN	All

Involved Region or Country	North America and Israel
Additional Options (RPOs)	Equipped with Diesel Engine (RPO LWN)
Condition	
	4754826



	aust of the tangental gen
Cause	This may be due to the charge air cooler pipe clamp not being tightened properly.
Correction	If you encounter a vehicle with the above concern, do not replace the turbocharger for this condition, instead tighten the charge air cooler pipe clamp.

Parts Information

No parts are needed for this concern.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4081608*	Tighten the Charge Air Cooler Duct Clamp	0.4 hr
*This is a unique Labor Operation for Bulletin use only.		

Service Procedure

Refer to Charge Air Cooler Inlet/Outlet Duct Replacement in SI for the procedure to gain access to the clamps needed to be tightened.

Version	2
Modified	August 29, 2017 — Added 2018 Model Year.