



# Service Bulletin

File in Section: -

Bulletin No.: 17-NA-194

Date: September, 2017

## INFORMATION

**Subject:** Information on Charge Air System Leaks, Malfunction Indicator Lamp (MIL) Illuminated - DTCs P0101, P0263, P0266, P0269, P0272, P0275, P0278, P0281, P0284, P0299, P0712, P11CC, P11DC, P2002, P2459, P2463, P2627, P200C, P200E, P20EE, P22B6 and/or P2A00 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016	2018			Diesel (RPO LWN)	
	Express						
GMC	Canyon						
	Savana						

<b>Involved Region or Country</b>	North America, Israel
<b>Condition</b>	<p>Some customers may comment that the MIL is illuminated. The technician may find one or more of the following DTCs set:</p> <ul style="list-style-type: none"> <li>• P0101</li> <li>• P0263</li> <li>• P0266</li> <li>• P0269</li> <li>• P0272</li> <li>• P0275</li> <li>• P0278</li> <li>• P0281</li> <li>• P0284</li> <li>• P0299</li> <li>• P0712</li> <li>• P11CC</li> <li>• P11DC</li> <li>• P2002</li> <li>• P2459</li> <li>• P2463</li> <li>• P2627</li> <li>• P200C</li> <li>• P200E</li> <li>• P20EE</li> <li>• P22B6</li> <li>• P2A00</li> </ul>
<b>Cause</b>	This condition may be caused by an induction system leak.
<b>Information</b>	<p>To locate a leak, it is recommended to perform a Charge Air Cooler Diagnosis (Full System Air Leak Test).</p> <ul style="list-style-type: none"> <li>• If you find a leak, charge the diagnostic to that part replacement or repair.</li> <li>• If you do not find a leak, add the time to whatever repair fixes the vehicle.</li> </ul>

### Parts Information

No parts are required for this repair.

Version	2
Modified	August 30, 2017 — Added 2018 Model Year.

