

Service Bulletin

File in Section:

Bulletin No.: 17-NA-264

Date: August, 2017

TECHNICAL

Subject: Diagnostic Tip for Malfunction Indicator Light (MIL) Illuminated, DTC P0106 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Engine.	
Chevrolet	Corvette	2017	2018			Equipped with 6.2L (RPO LT4)	

Involved Region or Country	North America and N.A. Export Regions		
Condition	Some customers may comment that the Malfunction Indicator Light (MIL) is illuminated. The technician may find DTC P0106 set.		
Cause	This condition may be caused by a software anomaly.		
Correction	An updated software calibration has been released to address this condition.		

Service Procedure

Reprogram the engine control module (ECM) with the latest calibrations available on TIS2WEB. Refer to *K20 Engine Control Module: Programming and Setup* in SI.

Important: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time	
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time	

Version	1
Modified	

