



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-277

Date: September, 2017

TECHNICAL

Subject: Left Front Window Inoperative

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2017	2017			All	All

Involved Region or Country	North America Only
Condition	Some customers may comment on the left front window is not going up or down, or may state that window travel is noisy.
Cause	This may be due to the window regulator cables being frayed or broken causing the window to jam or not to move up or down.
Correction	Replace the left window regulator if the cable is frayed and/or the cable is rubbing against the motor drum housing like illustrated above.

Service Procedure

If you encounter a vehicle with the above condition. Replace the left window regulator. Refer to *Front Side Door Window Regulator Replacement* in SI.

Parts Information

Causal Part	Description	Part Number	Side
X	REGULATOR ASM-FRT S/D WDO	42582714	Left

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2021410	Front Side Door Window Regulator Replacement	Use Published Labor Operation Time

Version	1
Modified	

