

Subject: Engineering Information – Excessive Tail Lamp Condensation

This PI has been revised to end the need for information from the field. Please discard PIE0392.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore	2017	2017			All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.