

1 11 04-17



Service Information Bulletin

SUBJECT	DATE
SPN 520960 (TCM)	December 2017

Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0140	DT12	SPN 520960 / FMI 7	This is a new diagnostic for DT12 Troubleshooting.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
 Telephone: 313-592-5000
www.demanddetroit.com

2 SPN 520960 / FMI 7

Unable to Shift Split Group Into Retracted Position

This fault indicates that the TCM detected a stuck/binding split pin during a shift request. Perform the split pin bushing repair. Refer to section "Split Rod Bushing Repair".