

---

<b>Reference</b>	SSM72369
<b>Models</b>	F-TYPE / X152
<b>Title</b>	X152 - Active exhaust valve 'Squeak' when operated
<b>Category</b>	Engine
<b>Last modified</b>	23-Jan-2017 00:00:00
<b>Symptom</b>	403000 Exhaust System Concerns
<b>Content</b>	<p><b>Issue:</b> Customers may report either a 'squeak' noise coming from the rear of the vehicle when the active exhaust valve is requested to open or close.</p> <p><b>Cause:</b> The active exhaust valve spindle shaft and bush contact area partially seize or in some extreme cases full seizure occurs.</p> <p><b>Action:</b> Parts have now been updated to include a Graphite Collar and bullet spindle to prevent this failure and are in service stock. Please only submit EPQR's for failures after <b>K18890</b>.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>