



Install Improved Driver and Front Passenger Seats

Classification Campaign Bulletin **Section/Group** 13 - Seats **Country/Region** United States

Year 2017 **Model** Model 3 **Version** All

Bulletin Classification: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

Condition

Certain front seats in Model 3 vehicles might have a reduced adjustment range or might make undesirable noise during use.

Correction

Install improved driver and front passenger seats for customer satisfaction.

Correction Description	Correction	Time
SB-17-13-003 Not Applicable	S011713003	0.00
Install Improved Driver And Front Passenger Seats	S021713003	1.10

Required Part(s):	Part Number	Description	Quantity
	7654322-01-A	M3 1R LH LHD SEAT COMPLETE	1
	7654324-01-A	M3 1R RH LHD SEAT COMPLETE	1
These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.			
Special Tool(s):	1133787-00-A	Key, Seat Belt Release, Model 3	

Procedure

Replace the driver and front passenger seats (refer to Service Manual procedure 13040102).

Affected VIN(s) Affected Model 3 vehicles built before approximately July 28th, 2017.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.