



Replace Headlights

Classification Campaign Bulletin **Section/Group** 17 - Electrical **Country/Region** United States

Year 2017 **Model** Model 3 **Version** All

Bulletin Classification: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

Condition

While current headlights are adequate, an upgraded version improves upon them. Replace the current headlights with the new version.

Correction

Replace the LH and RH headlights.

Correction Description	Correction	Time
SB-17-17-004 Not Applicable	S011717004	0.0
Replace LH and RH Headlights With Updated Parts	S021717004	1.1

Required Part(s):	Part Number	Description	Quantity
		One of the following:	
	1077371-88-E	RWK, HD/LP ASY, SAE UP-LEVEL, LH	1
	1077371-00-E	HD/LP ASY, SAE UP-LEVEL, LH	1
		One of the following:	
	1077372-88-E	RWK, HD/LP ASY, SAE UP-LEVEL, RH	1
	1077372-00-E	HD/LP ASY, SAE UP-LEVEL, RH	1

Procedure

Replace the LH and RH headlights (refer to Service Manual procedure 17400102).

Affected VIN(s) Affected Model 3 vehicles built before approximately August 23, 2017.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.

