VOLVO CAR SERVICE AND PARTS BUSINESS



# **Technical Journal**

## TITLE: Fuel pump unit updated method

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:		
TJ 32739.1.0	Technical Service	United States and Canada		
3 US 7	PARTNER:	ISSUE DATE:	STATUS DATE:	
	2510 Volvo Car USA	2017-11-01	2017-11-08	
FUNC GROUP: 2331	FUNC DESC: Fuel pump; feed pump	Page	1 of 3	

## "Right first time in Time"

### Attachment

File Name	File Size		
TJ 32739.pptx	0.8673 MB		

## Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124	96	B6324S2			0		2010-2011	21	-	200920-201020
124	98	B6324S			0		2007-2011	21	-	200620-201020
135	96	B6324S2			0		2010-2011	21	-	200920-201020
136	94	B6324S4			0		2011-2014	21	-	201020-201346
136	95	B6324S5			0		2011-2014	21	-	201020-201346
156	94	B6324S4			0		2011-2014	22	-	201020-201346
156	95	B6324S5			0		2011-2014	22	-	201020-201346
156	95	B6324S5			0		2011-2014	36	-	201020-201346
156	96	B6324S2			0		2010-2011	22	-	200920-201020
156	96	B6324S2					2010-2011	36	-	200920-201020

## **CSC** Customer Symptom Codes

Code	Description
AB	Starting/Engine hard to start/cranks slowly/Unsure when/at all times
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2017 VOLVO CAR USA, LLC



#### VST Operation Number

VST Operation Number	Description
23428-2	Fuel tank install-remove/replace

#### **DTC** Diagnostic Trouble Codes

#### Text

#### **DESCRIPTION:**

This TJ is to inform the market in cases where a fuel pump unit in the fuel tank needs to be replaced. Additional parts needs to be ordered due to an updated method.

#### **SERVICE:**

If a replacement of the fuel pump unit in the fuel tank is performed, an updated method in VIDA is released.

Additional parts (1 clip part number: 31478993 and 1 part number 999574 cable tie) needs to be ordered to be able to perform the method as stated above, see attachment.

This is to ensure that the harness is positioned correctly towards vehicle body to prevent chafing of harness.

#### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 2331.

## To view TJ attachment continue to next page. This TJ has one attachment.

TJ 32739



