



FAULT CODE CD0600 IN CENTRAL GATEWAY MODULE

MODEL

G30 (5 Series)

SITUATION

Discovered during vehicle diagnosis, Fault Code CD0600 "Ethernet unexpected linkdown" is recorded in Central Gateway Module (ZGW).

No malfunction perceptible to the customer.

CAUSE

Erroneous fault memory entry.

CORRECTION

None necessary.

PROCEDURE

For conditions that are similar to the situation described:

The fault code can be ignored. Do not replace parts or program the vehicle to try to eliminate the fault.



Note: This erroneous fault entry should not occur after 07/2017.

WARRANTY INFORMATION

For Information only

[Copyright ©2017 BMW of North America, Inc.]