



SERVICE ACTION: SUPPLEMENTARY PAGE NEEDED IN OWNER'S MANUAL

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

F22 (2 Series Coupe)	F23 (2 Series Convertible)	F30 (3 Series Sedan)	F31 (3 Series Sport Wagon)
F32 (4 Series Coupe)	F33 (4 Series Convertible)	F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)
F80 (M3 Sedan)	F82 (M4 Coupe)	F83 (M4 Convertible)	F87 (M2 Coupe)

SITUATION

Operator's manual of affected vehicles does not contain required information on wireless smartphone charging accessory.

AFFECTED VEHICLE

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

PROCEDURE

A supplementary sheet must be added to the Owner's Handbook **before vehicle delivery**.

An example of the sheet is attached for your reference.

If vehicles have already been delivered, the supplementary sheet is to be added to the Owner's Handbook **during the next service visit**.



Attention: The customer must be notified of the change to information in the

Owner's Handbook.

PARTS INFORMATION

Part Number	Description	Quantity

84 10 9 860 542

Supplementary Sheet

1

WARRANTY INFORMATION

Reimbursement for this Service Action repair campaign will be via normal claim entry utilizing the following information:

Defect Code:	0099780100	
Labor Operation:	Labor Allowance:	Description:
00 64 681	3 FRU	Adding a supplementary sheet to the Owner's Handbook

ATTACHMENTS

View PDF attachment [Attachment B84 09 16](#).

[Copyright ©2016 BMW of North America, Inc.]