



## INTERIOR REARVIEW MIRROR MOVES OUT OF POSITION

### MODEL

F54 (Cooper, Cooper S Clubman)	F55 (Cooper, Cooper S Hardtop 4 door)	F56 (Cooper, Cooper S Hardtop 2 door)	F57 (Cooper, Cooper S Convertible)
--------------------------------	---------------------------------------	---------------------------------------	------------------------------------

#### On vehicles with manual interior mirror

Without option:

SA 0430/0431 - automatically dimming internal mirrors or SA 0302 - Alarm system

### SITUATION

The “manually-dimming” interior rearview mirror does not hold its set position when traveling over rough roads and/or with “low ambient” interior temperatures.

### CAUSE

The pivot ball surface finish does not provide sufficient friction for stable positioning.

### CORRECTION

Replace mirror with the improved part.

### PROCEDURE

For conditions that are similar to the situation described:

Replace mirror with the standard EPC part number, per repair instructions “REP 51 16 063 Removing and Installing/replacing interior mirror”.



Note: Verifying the production date code for replacement (see graphic below for location). The date code on

part format is in “dd/mm/yy.”(May 12, 2016)



### PARTS INFORMATION

Part Number	Description	Quantity
Refer to EPC	Rear View Mirror (manually-dimming)	1

### WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty.

<b>Defect Code:</b>	<b>5116023700</b>	
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
51 16 060	Refer to KSD2	Removing and installing or replacing interior mirror (Main work)
Or		
51 16 560	Refer to KSD2	Removing and installing or replacing interior mirror (Plus work)

If you are using a Main labor code for another repair, use the Plus code labor operation 51 16 560 instead.

[ Copyright ©2017 BMW of North America, Inc. ]