



SERVICE ACTION: REMOVE XDRIVE NAME PLATE FROM TRUNK LID

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

G30 (5 Series PHEV)

AFFECTED VEHICLES

This Service Action involves 5 Series vehicles produced from February 28, 2017 to March 30, 2017.

Vehicles which require this Service Action or to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

SITUATION

The xDrive name plate on the left side of the trunk was incorrectly installed at the factory and needs to be removed.

CAUSE

The xDrive name plate on the left side of the trunk was incorrectly installed at the factory and needs to be removed.

CORRECTION

Remove the xDrive name plate from the left side of the trunk lid.

PROCEDURE



Remove the xDrive name plate from the left side of the trunk lid as per repair instruction "51 14 11 Replacing model name plate, rear".



Note: Do not pry on the name plate in order to remove. Using a cutting cord or strap makes removal easy and without damage.

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code:	0051160400	
Labor Operation:	Labor Allowance:	Description:
00 65 550	3 FRU	Removing the xDrive name plate (Plus work)

[Copyright ©2017 BMW of North America, Inc.]