



## CONSOLE STORAGE COMPARTMENT LID DOES NOT OPEN EASILY

### MODEL

F54 (Cooper, Cooper S, JCW Clubman)
-------------------------------------

### SITUATION

Center console storage compartment lid requires too much force to open as demonstrated in accompanying video.

[tinyurl.com/mkphrma](http://tinyurl.com/mkphrma)

### CAUSE

A. Sticky release mechanism.

And/or

B. Improper alignment.

### CORRECTION

A. Lubricate latch surfaces.

B. Loosen and reinstall center console lid.

### PROCEDURE

For conditions that are similar to the situation described:

Follow the attached Storage Compartment Lid Adjustment Procedure.

### PARTS INFORMATION

Part Number	Description	Quantity
83 23 0 309 627	Lubricant, Carbaflo KSP 105 (50g)	As needed
NPN	Cotton swab (Local source)	1

### WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty.

<b>Defect Code:</b>	<b>5116312900</b>	
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
51 16 228	Refer to KSD2	Removing and installing or replacing side trim cover on center console, both sides (Main work)
Or:		
51 16 728	Refer to KSD2	Removing and installing or replacing side trim cover on center console, both sides (Plus work)
And:		
51 99 000	2 FRU	Lubricate and adjust storage compartment lid

If you are using a Main labor code for another repair, use the Plus code labor operation 51 16 728 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 51 99 000 is not considered a Main labor operation. Also, since the "work time" FRU allowance to be claimed is specified, a separate punch time is not required.

### Sublet – Bulk Materials

<b>Sublet Code 4</b>	See sublet reimbursement calculation below	Reimbursement for the repair-related bulk materials (Do not use part numbers for claim submission)
----------------------	--	--

Sublet reimbursement calculation for claiming the used quantities of repair-related bulk materials:

- BMW part numbers is at dealer net plus your center's handling; and
- Other materials not available through BMW and obtained locally are at "cost plus 20 percent."

Enter this material cost in sublet and itemize the amount on the repair order in the claim comment section.

## ATTACHMENTS

View PDF attachment [M51 02 17 Attachment A](#).

[ Copyright ©2017 BMW of North America, Inc. ]