



SI M51 16 16
Body

May 2017
Technical Service

CAVITY PROTECTION WAX LEAKING OUT OF HOOD

MODEL

F56 (Cooper, Cooper S Hardtop 2 door)

F57 (Cooper, Cooper S Convertible)

Vehicles produced at the Nedcar (Born) plant.



Note: Nedcar vehicles can be identified by a “3” at the beginning of the 7-digit chassis number.

SITUATION

Cavity protection applied to underside of hood is leaking out onto wheel arch trim and grille.



CAUSE

Improper application of Cavity Protection Wax

CORRECTION

Remove current cavity protection and reapply.

PROCEDURE

For conditions that are similar to the situation described, refer to the attachment for detailed repair information.

PARTS INFORMATION

--	--	--

Part Number	Description	Quantity
83 12 0 390 086	BMW Cavity Protection Wax Remover (125ml)	1
83 42 0 428 190	BMW Cavity Protection Wax (400ml)	1

WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty as applicable.

Defect Code:	5197024900	
Labor Operation:	Labor Allowance:	Description:
41 61 000*	Refer to KSD	Removing and Installing Bonnet (Main Work)
41 61 600	Refer to KSD	Removing and Installing Bonnet (Plus Work)
51 99 000	8 FRU	Removing excess cavity wax and reapplying correct amount of cavity protection wax.

Labor operation code 41 61 000 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 41 61 600 instead.

ATTACHMENTS

View PDF attachment [Attachment A SIM51 16 16](#).

[Copyright ©2017 BMW of North America, Inc.]