



# Preliminary Information

## PIP5515 Repeat MIL On P2097

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2018	All	All	1.5L L3A	All

Involved Region or Country	North America
Condition	Repeat MIL On P2097
Cause	Under Investigation At This Time.

### Correction:

Some customers may comment that the MIL has come on.

DTC P2097 may be set current or in history.

Confirm that the latest calibrations from 17058 have been installed.

If the calibrations are current, perform the diagnostic in Service Information for the code.

If the diagnostic for the code fails to isolate the cause of the concern, do not attempt repairs at this time.

Clear codes and return the vehicle to the customer.

Advise the customer that GM is aware of this concern and is working on a resolution.

### Version History

Version	1

