



Preliminary Information

PIP5481A Check Engine Light On With DTC P026A and a Snow Plow Installed

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	6.6 L5P	All
GMC	Sierra	2017 - 2018	All	All	6.6 L5P	All
Involved Region or Country	North America					
Additional Options (RPO)	6.6 L5P					
Condition	Some customers may comment on a Service Engine Soon Light / Check Engine Light on. Technician may find DTC P026A and a snow plow installed.					
Cause	Under Investigation.					

Correction:

Please refer to the owner's manual under Adding a Snow Plow or Similar Equipment (In Service Information it will be Document ID 4501631). It states:

Caution: Do not exceed 72 km/h (45 mph) with a snow plow mounted to the vehicle. The vehicle could overheat and be damaged.

However, GM engineering is aware of this concern and is investigating.

This Preliminary Information will be updated when further information is available.

Version History

Version	2
Modified	8/31/2017 to add 2018 model year.

