

Trunk lid chrome trim loose

Topic number	LI88.85-P-066992
Version	1
Function group	88.85 Trim strips
Date	08-31-2017
Validity	Model 238.3xx E Class coupe
Reason for change	
Reason for block	

Complaint:

Chrome trim at rear area of trunk lid is loose

Cause:

Adhesion between chrome trim and painted trunk lid area

Remedy:

Remove installed trim piece and clean the area of all adhesives.

Do not attempt to reinstall or repair the original trim piece.

Install new part number chrome trim A238740000028

Symptoms						
Body / Body/Cab / Trim strip/cover / Missing						
Body / Body/Cab / Trim strip/cover / Damaged						
Body / Body/Cab / Trim strip/cover / Detaches						
Body / Body/Cab / Trim strip/cover / Inaccurate fit						

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 238 740 00 00	28		Moulding	1		X