Topic number	LI82.20-P-067044	
Version	1	
Function group	82.20 Interior lights	
Date	09-19-2017	
Validity	213, 222, 238 (MY18 only)	
Reason for change		
Reason for block		

Complaint: Operational complaints of ambient lighting

Cause: Various

Remedy:

Situationally dependant on the symptoms

IMPORTANT: The ambient lighting is operated over the LIN bus and are controlled via the ambient lighting control unit. The head unit is only for making settings. Therefore replacing the head unit and wiring harnesses may not remedy the complaint.

The repair must be established in individual situations. Please create a PTSS case with the following information:

- Quick test

- Ambient lighting control unit log
- Video showing the operating steps and settings in the head unit with a few words of explanation.
- Since when does the fault occur, under what specific conditions and with which head unit settings?
- Are there certain conditions under which the fault does not occur?
- Can the fault be temporarily rectified, and if so, how?
- Please record and attach a body CAN trace with XENTRY SDscan.

Guidance will be provided in the PTSS case response

Symptoms

Overall vehicle / Lighting / Interior illumination / Ambiance illumination / Does not go on

XENTRY TIPS

Validity		
Vehicle	Engine	Transmission
E (213)	*	*
E (238)	*	*
S (222)	*	*