

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2017040005, July 2017

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 231, Model Year 2017**
Retrofit TIREFIT Kit

Daimler AG ('DAG'), the manufacturer of Mercedes-Benz vehicles, has determined that in certain SL-Class (231 platform) vehicles, the TIREFIT kit may possibly be missing. An authorized Mercedes-Benz dealer will retrofit the TIREFIT kit on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 238 vehicles are affected.

Order No. P-SC-2017040005

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

1. Retrofit TIREFIT in trunk (Figure 1).



Figure 1

Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	TIREFIT container (620ml)	A 000 583 07 12	100%
1	Tire inflation compressor	A 000 583 15 02	100%
1	Support (vehicles without code 811)	A 231 684 03 00 9051	100%
1	Support (vehicles with code 811)	A 231 684 00 00 9051	100%

- i** The codes correspond to:
- 811 – HIGH END SOUND SYSTEM.

- i** **Note:**
- Please be aware that only the part number(s) referenced in the Campaign Bulletin is/are approved for use to repair the vehicle. Repairs performed using any other part(s) will not have been performed in accordance with the campaign. Accordingly, warranty claims submitted with reference to an improper part number(s) will be denied.
 - The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Retrofit TIREFIT in trunk (02-9918)

Damage Code	Operation Number	Labor Time (hrs.)
40-910-37-7	02-9918	0.2

**Note**

Operation Number labor times are subject to change.