

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2017080007, October 2017

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 217 Model Year 2017**
Apply Preservation Agent to Underbody

Daimler AG ('DAG'), the manufacturer of Mercedes-Benz vehicles, has determined that on certain S-Class Coupe (217 platform) vehicles the mounting console for the underbody paneling does not correspond to the current production configuration. The surface of the mounting console may have been damaged as a result of a process malfunction. An authorized Mercedes-Benz dealer will apply preservation agent to the left and right rear underbody paneling on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 141 vehicles are affected.

Order No. P-SC-2017080007

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

1.  Remove left and right rear underbody paneling on the sides.
2. Apply preservation agent to mounting consoles on left and right rear underbody (Figure 1).



Figure 1 Shown on right rear

3.  Assemble in the reverse order.

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
0.1*	Cavity preservation	A 000 986 72 70 10	100%

* Use 1 packaging unit for 10 vehicles.

Warranty Information

Operation: Apply preservation agent to underbody on left and right rear (02-2021)

Damage Code	Operation Number	Labor Time (hrs.)
52 900 34 8	02-2021	0.9

Note

Operation Number labor times are subject to change.