Service Update

17216 Electronic Brake Control Module Cannot Be Reprogrammed



Reference Number: N172100970 Release Date: June 2017

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the

dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited

Warranty period.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Impala	2017	2017	KSG/FX3	Adaptive Cruise/Auto Ride Cntrl

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	On certain vehicles, the electronic brake control module (EBCM) is not able to be unlocked due to a		
	mismatch between programming seed and device key. Module unlock allows for a calibration or software		
	update used for service or vehicle content change.		
Correction	Dealers are to replace the electronic brake control module.		

Parts

Quantity	Part Name	Part No.	
1	Module Asm-Elek Brk Cont (W/ brkt & Brk Press Mod VIv)	84092231	

It is estimated that only less than 51 of the involved vehicles worldwide will require parts replaced on this vehicle. There is a small number of vehicles anticipated that will need this fix. Due to limited initial parts availability, dealers are encouraged not to order recall parts for use as shelf stock. Parts may have quantity limiters in effect.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status.

Warranty Information

Labor	Description	Labor	Trans.	Net
Operation		Time	Type	Item
9103205	Electronic Brake Control Module Replacement (Includes Brake Bleed and Programming)	1.8	ZFAT	N/A

Service Procedure

Replace the electronic brake control module. Refer to Electronic Brake Control Module Replacement in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.



GLOBAL SAFETY FIELD INVESTIGATIONS DCS4473 URGENT - DISTRIBUTE IMMEDIATELY

Date: June 13, 2017

Subject: 17216 - Service Update

Electronic Brake Control Module Cannot Be Reprogrammed

Models: 2017 Chevrolet Impala

Equipped with KSG/FX3 (Adapt Cruise/Auto Ride Cntrl)

To: All General Motors Dealers

General Motors is releasing Service Update 17216 today. The total number of U.S. vehicles involved is approximately 51. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated June 13, 2017. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS