

## Service Bulletin

Bulletin No.:

n No.: 16-NA-207 Date: October, 2017

# TECHNICAL

#### Subject: Buzzing Noise Heard and/or Vibration Felt in Shifter Assembly and/or Shifter Console During Aggressive Driving and Parking Maneuvers After Vehicle has Warmed Up

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2018				

Involved Region or Country	North America and N.A. Export Regions	
Condition	The customer may comment on a buzzing noise from the I/P area under heavy acceleration and most noticeable after the vehicle engine has warmed up.	
Cause	This may be caused by the weight on the shifter cable expanding due to thermal cycling and allowing the cable to move resulting in noise.	
Correction	If the shifter cable has been found to be the cause of the customer concern, the shifter cable must be replaced.	

#### Service Procedure

Refer to Range Selector Lever Cable Replacement in SI.

### **Parts Information**

Refer to the Electronic Parts Catalog (EPC) to determine the proper part numbers required for the selector level cable, if replacement is required.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8460370	Range Selector Lever Cable Replacement	Use Published Labor Operation Time

Version	2
Modified	Sept. 25, 2017 - Update Model Year to 2018 and revised Condition, Cause and Parts Information section.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION